

# BELZONA KEEPS TENANTS DRY AND HAPPY

ID: 6197

Industry: *Buildings & Structures*

Customer Location: *office complex, Brisbane, Queensland, Australia*

Application: *RPA-Roof Problem Areas*

Application Date: *July 2012*

Substrate: *Concrete*

Products: *\* Belzona 4111 (Magma Quartz),  
\* Belzona 4151 (Magma Quartz Resins),  
\* Belzona 3111 (Flexible Membrane),*

## Problem

*Cracks in the flat roof were allowing water to penetrate into the offices below.*



## Photograph Descriptions

\* 1. Original roof condition 2. Cracks in roof 3. Defects in the roof that needed repair 4. The finished application after application of the Belzona 3111 system ,

## Application Situation

High Rise Office complex in the Brisbane Central Business District.

## Application Method

Application was carried out in accordance with Belzona System Leaflet RPA-1. After high pressure washing and drying the roof, cracks and defects revealed during the cleaning process were filled using the Belzona 4151 or Belzona as appropriate. A fully reinforced Belzona 3111 system was then applied over vthe entire roof area.

## Belzona Facts

The Belzona 3111 system was chosen as it provided the required level of performance and longevity. The client was looking to achieve a long term solution with minimal disruption

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)

