

BELZONA EXPANSION JOINT SEALANT FOR CORPORATE OFFICE

ID: 62

Industry: General Industry

Customer Location: Corporate offices of Tennessee power company

Application: FPA-Floor Problem Areas


Application Date: 1988

Substrate: Brick

Products: * Belzona® 2221 (MP Fluid Elastomer) ,

Problem

Existing sealant breaking loose, creating a pedestrian safety hazard.



Photograph Descriptions

- * The application was carried out with the in-house maintenance staff of the power company. Closed cell foam backer rod being inserted. ,
- * Applying Belzona® 2221. ,
- * Expansion joint sealed. ,

Application Situation

Expansion joints on brick floors

Application Method

The application was carried out in accordance with Belzona Know-How Leaflet FPA-6.

Belzona Facts

All expansion joints were sealed with approximately \$30,000 in Belzona product. Nearly ten years after, they are still in good shape.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024