

# BELZONA EXPANSION JOINT SEALANT FOR CORPORATE OFFICE

ID: 62

Industry: *General Industry*

Customer Location: *Corporate offices of Tennessee power company*

Application: *FPA-Floor Problem Areas*

Application Date: *1988*

Substrate: *Brick*

Products: *\* Belzona® 2221 (MP Fluid Elastomer) ,*

## Problem

*Existing sealant breaking loose, creating a pedestrian safety hazard.*



## Photograph Descriptions

- \* The application was carried out with the in-house maintenance staff of the power company. Closed cell foam backer rod being inserted. ,
- \* Applying Belzona® 2221. ,
- \* Expansion joint sealed. ,

## Application Situation

Expansion joints on brick floors

## Application Method

The application was carried out in accordance with Belzona Know-How Leaflet FPA-6.

## Belzona Facts

All expansion joints were sealed with approximately \$30,000 in Belzona product. Nearly ten years after, they are still in good shape.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)

