

BELZONA 4111 BETTER THAN CONCRETE

ID: 621

Industry: Buildings & Structures
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona 4111 (Magma-Quartz) ,
* Belzona 4911 (Magma TX Conditioner) ,

Customer Location: Mass Transit Company, South Texas
Application Date: January 2005

Problem

Heavy buses rolling over drainage channel cracked the concrete curb. Client also wanted to compare Belzona 4111 to concrete as a repair material in side by side comparison.



Photograph Descriptions

- * Damaged drainage channel curb ,
- * Area prepared and conditioned with Belzona 4911 ,
- * Belzona 4111 layer in place ,
- * Completed application ,

Application Situation

Drainage channel at entrance to bus depot. "Speed hump" also required to control traffic entering depot

Application Method

Application carried out in accordance with Belzona Know-How System Leaflet FPA-1.

Belzona Facts

After almost one year, Belzona 4111 still in tact while the concrete had not held up in this heavily trafficked bus depot. Repairs carried out quickly with minimal disruption to traffic.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve