

BELZONA REPAIRS AT LOCAL SCHOOL

ID: 625

Industry: *Buildings & Structures*

Customer Location: *High School - Grant County, West Virginia U.S.A.*

Application: *TCC-Tanks and Chemical Containment Areas*

Application Date: *September 2005*

Substrate: *Steel*

Products: ** Belzona® 1111 (Super Metal) ,*

Problem

Deterioration of steel due to daily contact with chlorine.



Photograph Descriptions

- * Overview of the working area ,
- * Repairs in progress accelerating the cure time ,
- * Completed repairs ,

Application Situation

Erosion-corrosion on a 6,000 gallon water tank clarifier

Application Method

Application was carried out in accordance with Belzona System leaflet TCC-1.

Belzona Facts

Welding in this instance would have been costly and time consuming due to the limited space and working in over 6 feet of water, Belzona® 1111 was therefore used. The Belzona solution was completed in two hours as compared to a whole day with a traditional repair approach and the school stayed open during this entire time.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com

