

Belzona repairs swimming pool

ID: 6253

Industry:

Application: FPA-Floor Problem Areas

Substrate: concrete

Products: * Belzona 4151 (Resin) ,
* Belzona 4911 (TX Conditioner) ,
* Belzona 4111 (Magma-Quartz) ,

Customer Location: Kwidzyn (Poland)

Application Date: May 2011

Problem

A significant water leak from the pool due to the crack of the concrete.



Photograph Descriptions

- * 1. General view of the damaged bases ,
- * 2. The bottom of the pool after the application of Belzona 4151 ,
- * 3. Supplementing concrete damage - Belzona 4111. ,
- * 4.General view of the swimming pool. ,

Application Situation

Concrete crack on the bottom of the swimming pool .

Application Method

The Application was carried out in accordance with Belzona Know-How FPA 1

Belzona Facts

Previous repairs to other materials did not cause inhibition of the leak. Removed loose and wet concrete parts. The entire exposed concrete was painted Belzona4151. At the end of applied Belzona 4111.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are

manufactured under an ISO

9000 Registered Quality

Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024