

BELZONA CURES DRUG FACTORY FLOOR

ID: 6255

Industry: Food & Drink

Customer Location: Pharmaceutical company, Warsaw, Poland

Application: FPA-Floor Problem Areas

Application Date: June 2013

Substrate: concrete

Products: * Belzona 4111 (Magma Quartz),
* Belzona 5811 (immersion Grade),

Problem

The cracks collect a lot of bacteria and contaminants creating a serious hygiene issue.



Photograph Descriptions

* 1. View of damaged warehouse floor 2. Close up of the cracked concrete 3.and 4. The floor after application of Belzona 5811 ,

Application Situation

Very damaged and cracked concrete floor in the medicines factory.

Application Method

Application was carried out in accordance with Belzona System Leaflets FPA-1 and FPA-3.

Belzona Facts

Solvent free Belzona system enabled floor repairs to be carried out with minimal disruption to production in adjoining areas. Belzona repair provided a smooth, easy clean, hygienic surface suitable for pharmaceutical production.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve