

BELZONA LEVELS TAXI STAND

ID: 6256

Industry: Buildings & Structures

Customer Location: Shopping centre, Brisbane, Queensland, Australia

Application: FPA-Floor Problem Areas

Application Date: December 2013

Substrate: Concrete

Products: * Belzona 4111 (Magma Quartz),

Problem

The concrete slab, adjacent to the ramp for the taxi stand, had sunk and created a step that had become a trip hazard. This had also made wheelchair access difficult.



Photograph Descriptions

- * 1. The taxi stand ramp ,
- * 2. Close up showing the step between the ramp and road with surface preparation underway ,
- * 3. The finished application ,
- * 4. Three years on and still in perfect condition ,

Application Situation

Taxi Stand drop off point at shopping centre

Application Method

This application was carried out in accordance with Belzona System Leaflet FPA-1. Belzona 4111 was used to re-profile the ramp creating a smooth transition from the road onto the footpath.

Belzona Facts

Belzona 4000 series materials are the product of choice for this busy shopping centre because they allow repairs to be carried out quickly and easily with minimum disruption and at the same time provide long term, permanent repairs. Even after 3 years of constant use , the ramp is still performing well with no signs of deterioration or cracking

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve