

PUMP REPAIR AND EFFICIENCY ENHANCEMENT WITH BELZONA

ID: 626

Industry: *Fluid Flow*

Application: *CEP-Centrifugal Pumps*

Substrate: *Brass and cast iron*


Products: ** Belzona® 1111 (Super Metal) ,
* Belzona® 1341 (Supermetalgilde) ,*

Customer Location: *Drinking Water Supplier, Portugal*

Application Date: *February 2004*

Problem

The pump had significant corrosion.



Photograph Descriptions

- * The severe localised corrosion ,
- * Application of Belzona® 1111 ,
- * The completed repair ,

Application Situation

Large horizontal split case pump housing

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet CEP-10.

Belzona Facts

The client realised a 7% increase in efficiency.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve