

BELZONA REBUILDS CRACKED WATER CHANNELS AT OUTDOOR POOL

ID: 6263

Industry:

Application: WPA-Wall Problem Areas

Substrate: Concrete

Products: * Belzona 4111 (Magma-Quartz) ,

Customer Location: Coquitlam, BC

Application Date: April 2015

Problem

The pool gutter system had developed major cracks in various areas allowing water to escape.



Photograph Descriptions

- * Extent of cracks needing rebuilding ,
- * Surface preparation underway using a hand grinder to clean and remove all loose material ,
- * A completed section of repair ,
- * Completed application ,

Application Situation

The water channel at outdoor pool.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-1

Belzona Facts

This was part of major refurbishment project to rehabilitate this outdoor swimming pool. A previous similar project had performed extremely well with no maintenance problems over the a perid of 5 years.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve