

# BELZONA ROOF REPAIRS AT PROMINENT RETAILER

ID: 6271

Industry: Commercial Facilities  
Application: RPA-Roof Problem Areas  
Substrate: Concrete  
Products: \* Belzona 3111 (Flexible Membrane) ,

Customer Location: Department store, NSW, Sydney  
Application Date: December 2004

## Problem

*Leaking joints were causing disruption to staff and shoppers at this high end department store.*



## Photograph Descriptions

\* 1. The leaking joints 2. Masking off before starting application 3. Conditioned joints 4. Application of Belzona 3111 in progress ,

## Application Situation

Roof leaks on a Department store roof.

## Application Method

Application was carried out in accordance with Belzona System Leaflet RPA-1. A fully reinforced Belzona 3111 system was applied to span across the joints.

## Belzona Facts

Belzona 3111 was chosen because it only needed to be applied at the problem joints so making application quick and simple.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve

Copyright © Belzona International Limited 2024