

BELZONA ROOF REPAIRS AT PROMINENT RETAILER

ID: 6271

Industry: Commercial Facilities
Application: RPA-Roof Problem Areas
Substrate: Concrete
Products: * Belzona 3111 (Flexible Membrane) ,

Customer Location: Department store, NSW, Sydney
Application Date: December 2004

Problem

Leaking joints were causing disruption to staff and shoppers at this high end department store.



Photograph Descriptions

* 1. The leaking joints 2. Masking off before starting application 3. Conditioned joints 4. Application of Belzona 3111 in progress ,

Application Situation

Roof leaks on a Department store roof.

Application Method

Application was carried out in accordance with Belzona System Leaflet RPA-1. A fully reinforced Belzona 3111 system was applied to span across the joints.

Belzona Facts

Belzona 3111 was chosen because it only needed to be applied at the problem joints so making application quick and simple.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve