

BELZONA SEALS PARAPET WALL

ID: 6276

Industry: Commercial Facilities
Application: RPA-Roof Problem Areas
Substrate: Concrete & Asphalt
Products: * Belzona 3111 (Flexible Membrane) ,

Customer Location: Shopping Centre, NSW, Australia
Application Date: July 2004

Problem

Ingress of water into the building below caused by failed sealant on the parapet wall joints.



Photograph Descriptions

* 1. Preparation in progress 2. Surface Conditioner applied 3. completed application ,

Application Situation

Parapet wall on the roof of a Shopping Centre

Application Method

Application was carried out in accordance with Belzona System Leaflet RPA-8. A fully reinforced Belzona 3111 system was applied to bridge between roof deck and wall.

Belzona Facts

Belzona 3111 was used for its easy application and ability to seal multiple substrates whilst coping with the differential movement present at the flashing.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

Copyright © Belzona International Limited 2024