

# BELZONA SEALS PARAPET WALL

ID: 6276

Industry: *Commercial Facilities*  
Application: *RPA-Roof Problem Areas*  
Substrate: *Concrete & Asphalt*  
Products: *\* Belzona 3111 (Flexible Membrane) ,*

Customer Location: *Shopping Centre, NSW, Australia*  
Application Date: *July 2004*

## Problem

*Ingress of water into the building below caused by failed sealant on the parapet wall joints.*



## Photograph Descriptions

\* 1. Preparation in progress 2. Surface Conditioner applied 3. completed application ,

## Application Situation

Parapet wall on the roof of a Shopping Centre

## Application Method

Application was carried out in accordance with Belzona System Leaflet RPA-8. A fully reinforced Belzona 3111 system was applied to bridge between roof deck and wall.

## Belzona Facts

Belzona 3111 was used for its easy application and ability to seal multiple substrates whilst coping with the differential movement present at the flashing.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve