

# BELZONA SAFETY FLOORING AROUND MIXER

ID: 6279

**Industry:** General Industry  
**Application:** FPA-Floor Problem Areas  
**Substrate:** Concrete  
**Products:** \* Belzona 4111 (Magma Quartz) ,  
\* Belzona 4411 (Granogrip) ,

**Customer Location:** Ceramics producer, Gliwice, Poland  
**Application Date:** May 2011

## Problem

The floor was covered with a rubber lining which was very slippery when Glycol was spilt on it. One worker had broken a foot after slipping on the floor.



## Photograph Descriptions

- \* 1. Grinding concrete floor ,
- \* 2. Repair of damage and filling cavities with Belzona 4111 ,
- \* 3. Application of Belzona 4411 ,
- \* 4. General view of the floor after application of Belzona 4411 system ,

## Application Situation

The floor lined with rubber lining around a mixer handling Glycol and other additives.

## Application Method

The application was carried out in accordance with Belzona System Leaflet FPA-8. After removing rubber sheets and cleaning the concrete, Belzona 4111 was used to level the concrete before applying the Belzona 4411 non-slip system.

## Belzona Facts

After application of Belzona 4411 floor is safe and there have been no more slips. Belzona 4411 provides a chemical resistant surface that makes clean-up of spills easy whilst providing a positive grip surface to prevent slips.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve