NEW BELZONA FLOOR FOR NEW SHOWROOM

ID: 6280

Industry: Commercial Facilities Customer Location: Car showroom, Nowra, NSW, Australia

Application: FPA-Floor Problem Areas Application Date: January 2005

Substrate: Concrete

Products: * Belzona 5231 (SG Laminate),

Problem

The showroom and workshop floors needed to be sealed with a high quality floor covering to enhance the appearance and protect it from the daily traffic of cars and pedestrians.









Photograph Descriptions

- * 1. Floor prior to coating,
- * 2. Preparation complete, vacuuming up the dust,
- * 3. Application underway,
- * 4. Application complete and being inspected by the client ,

Application Situation

New build flagship car showroom

Application Method

The application was carried out in accordance with Belzona System Leaflet FPA-3. The newly laid floor was allowed to dry out thoroughly before being prepared for coating by diamond grinding to remove surface laitence. After vacuuming to remove dust, the floor was coated with two coats of Belzona 5231.

Belzona Facts

Belzona 5231 was chosen for its durability, hard wearing properties and inbuilt grip system that minimised potential slip issues for cars and people. Its fast application and cure time meant that the showroom was finished in time for the scheduled opening.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve