

# BELZONA REFURBISHED LOADING DOCK STILL GOOD 7 YEARS ON

ID: 6281

Industry: Buildings & Structures

Customer Location: Business complex, Brisbane,  
Queensland, Australia

Application: FPA-Floor Problem Areas

Application Date: May 2009




Substrate: Concrete

Products: \* Belzona 5231 (SG Laminate),

\* Belzona 4411 (Granogrip),

## Problem

The Loading dock and car park were old and in need of a facelift as all of the original coating had been worn away.



## Photograph Descriptions

\* 1. The original condition of the floor area 2. Surface preparation in progress 3. The finished application showing the coated floor and reinstated lines, wording and chevrons 4. The floor after 7 years in service ,

## Application Situation

Loading dock and car park of a multi use business complex.

## Application Method

The application was carried out in accordance with Belzona System Leaflets FPA-4 and FPA-8. The floor area was prepared using a dustless diamond grinder then coated with 2 coats of Belzona 5231. The line markings, chevrons and wording were then reinstated using Belzona 4411 in a single coat of safety yellow.

## Belzona Facts

Belzona materials were chosen due to their ease of application, proven longevity and incorporated grip system that provides a safer and more durable finish than conventional floor paints. This decision has proven to be the right one as the floor is still in a serviceable condition 7 years later

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)

