BELZONA SEALS HIGH 270° CIRCULAR PARAPET WALL

ID: 6290

Industry: Buildings & Structures Customer Location: Coquitlam, BC
Application: RPA-Roof Problem Areas Application Date: August 2015

Substrate: Face bricks

Products: * Belzona 3911 (PSC Surface Conditioner)
 > Belzona 3111 (Flexible Membrane) ,

* Belzona 9311 (Reinforcement sheet),

Problem

The feature 270° circular parapet wall constructed of face bricks had been a constant source of water leaks since it was built and continued to develop new leaks as materials failed to withstand the movement they were subjected to.









Photograph Descriptions

- * 1.View of wall being pressure washed prior to application. It was established at this point that the bricks may have been sealed at some points creating a possible adhesion problem.
- * 2.The brick surface being ground to ensure adequate adhesion,
- * 3.Application of Belzona 3911,
- * 4. Application of 1st coat of Belzona 3111 completed. ,

Application Situation

The face bricks of a circular parapet wall

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-1. All contamination was removed

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA

Belzona Facts Belzona 3111 has good record of been able to protect parapet type walls where movement is a constant problem. Belzona 3911 was applied. Lay out Belzona 9311 over the conditioned area to be treated. Belzona 3111 was applied over the Belzona 9311.	