

BELZONA REPAIRED CAR PARK JOINT STILL INTACT

ID: 6294

Industry: *Buildings & Structures*
 Application: *FPA-Floor Problem Areas*
 Substrate: *Concrete*
 Products: ** Belzona 4111 (Magma Quartz),*

Customer Location: *Shopping Centre, Brisbane, Australia*
 Application Date: *June 2013*

Problem

The edge nosings of the concrete slabs had been broken down to rubble after years of daily traffic making them unsightly and dangerous



Photograph Descriptions

- * 1. The damaged floor joint ,
- * 2. Conditioned and ready for repair ,
- * 3. Repairs in progress ,
- * 4. Repaired joint 3 years after completion ,

Application Situation

The floor joint between concrete slabs in a Car Park

Application Method

Application was carried out in accordance with Belzona System Leaflet FPA-1. The old damaged concrete was removed and cut back to a sound substrate. The area was then prepared and rebuilt with the Belzona 4111 system to restore the original profile.

Belzona Facts

Belzona 4111 was used for its high strength, fast curing and ease of application. The floor repair is still in good condition more than

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
 FS 695214
 ISO 14001:2015
 EMS 695213

Belzona products are
 manufactured under an ISO
 9000 Registered Quality
 Management System.

www.belzona.com


BELZONA
 Repair • Protect • Improve

3 years later.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

