

80 TONNE BULLDOZER TRACKS-NO PROBLEM FOR BELZONA

ID: 6296

Industry: *General Industry*

Customer Location: *Workshop floor, Kwinana, Western Australia*

Application: *FPA-Floor Problem Areas*

Application Date: *November 2015*

Substrate: *Reinforced Concrete*

Products: ** Belzona 4111 (Magma Quartz),*

Problem

The workshop floor had been damaged by the caterpillar tracks making 180 degree turns tearing up the concrete.



Photograph Descriptions

* 1. The damaged concrete floor 2. Another area of damage 3. Close up of the repaired area 4. View of the workshop showing repairs ,

Application Situation

Workshop Floor where large, 80 Tonne bulldozers and excavators are maintained.

Application Method

Application was carried out in accordance with Belzona System Leaflet FPA-1. The floor area was badly damaged and had to be dug out to provide a suitable surface for rebuilding. Once done the area was re-built to the original level using the Belzona 4111 system.

Belzona Facts

Belzona 4111 was chosen after a successful trial area proved the extremely hard wearing and high load bearing properties of the product. The fast curing nature of the material was also a consideration as it meant the workshop could remain operational during repairs.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve