

BELZONA SEALS BROKEN SKYLIGHTS

ID: 6297

Industry: *Buildings & Structures*
Application: *RPA-Roof Problem Areas*
Substrate: *Bitumen*
Products: ** Belzona 3111 (Flexible Membrane) ,*

Customer Location: *Office building, Bielsko-Biala, Poland*
Application Date: *July 2009*

Problem

Under the influence of the sun skylights had broken around the fastening bolts allowing leakage of water into the rooms below whenever it rained.



Photograph Descriptions

* 1. Washing damaged skylights 2. Application of Belzona 3111 onto the Belzona 3911 Conditioner 3. Rooftop view immediately after the repair. 4. Rooftop view August 2016 ,

Application Situation

Roof above the office space has 4 large skylights.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-3.

Belzona Facts

Repair cost less than half the purchase and replacement costs of new skylights. Inspected in August 2016 repairs still in excellent condition and keeping offices dry.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve