

BELZONA REPLACES EXPANSION JOINTS IN OLYMPIC SIZED LAP POOL

ID: 6299

Industry: *Buildings & Structures*

Customer Location: *Ladysmith, BC*

Application:

Application Date: *March 2010*

Substrate: *New concrete*

Products: ** Belzona 2211 (MP Hi-Buid Elastomer) ,
* Belzona 2221 (MP Fluid Elastomer) ,*

Problem

Despite formulation improvements in the concrete manufacturing process, the final product is still susceptible to all forms of chemical attack.



Photograph Descriptions

- * 1. Overall view of the size of the facility ,
- * 2. Old flexible jointing material being removed. ,
- * 3. Application of Belzona 2211/2221 ,
- * 4. Completed application after masking tape has been removed. ,

Application Situation

The expansion joints of a pool suffering from chemical attack.

Application Method

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet HEX-13b. The old jointing material was completely removed prior to application. Concrete substrate was roughed and cleaned and then Belzona 2211 and 2221 were injected into the joint before being troweled into place.

Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com



Over the years, Belzona has provided many successful solutions to problems specific to wastewater treatment facilities. These include protection and repair of both new and old facilities and equipment.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

