

BELZONA PROVIDES FOOD FOR THOUGHT

ID: 632

Industry: General Industry Customer Location: Food Processing Plant, Manchester UK

Application: VPF-Valves, Pipes and Fittings Application Date: July 1999

Substrate: Mild Steel

Products: * Belzona® 1111 (Super Metal),

* Belzona® 6111 (Liquid Anode), * Belzona® 5111 (Ceramic Cladding),

Problem

Several holes in the weld seams and isolated pinholes. All surfaces showed signs of corrosion and existing paint work was cracked and peeling.







Photograph Descriptions

- * Exhaust duct outlet ,
- * Exhaust duct bend ,
- * Exhaust duct repaired,

Application Situation

Large exhaust duct bend

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets VPF-1 and VPF-2.

Belzona Facts

This system was selected to provide long term protection in the wet and polluted atmospheric conditions. This was coupled with its excellent appearance. The application is still performing well after six years.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair : Protect : Improve