

BELZONA REPAIRS HOLES WITH BULKFILL AND MAGMA QUARTZ

ID: 6324

Industry: Buildings & Structures
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona 4111 (Magma-Quartz) ,
* Belzona 4124 (Bulkfill) ,

Customer Location: Truck Part Manufacturer, NC, USA
Application Date: June 2016

Problem

Due to continuous forklift traffic holes had formed causing an issue in operations.



Photograph Descriptions

- * 1. Preparing hole by removing loose material ,
- * 2. After preparation ,
- * 3. Bulkfilling with Belzona 4124 ,
- * 4. Top coated with Belzona 4111 ,

Application Situation

Forklift traffic over control and expansion joint areas.

Application Method

The holes were cleaned out and filled with Belzona 4124. Once the holes were filled, it was top coated with Belzona 4111. FPA-1 System Leaflet was followed.

Belzona Facts

Customer saved a lot of money because there is a tunnel under the areas where the repair was done. Concrete was an option, but it would be a long and costly repair, and would eventually fail again. It took 1 day of labor to do the work. This Belzona system was used because it is proven to work and last a long, long time.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve