

# BELZONA REPAIRS HOLES WITH BULKFILL AND MAGMA QUARTZ

ID: 6324

**Industry:** Buildings & Structures  
**Application:** FPA-Floor Problem Areas  
**Substrate:** Concrete  
**Products:** \* Belzona 4111 (Magma-Quartz) ,  
\* Belzona 4124 (Bulkfill) ,

**Customer Location:** Truck Part Manufacturer, NC, USA  
**Application Date:** June 2016

## Problem

*Due to continuous forklift traffic holes had formed causing an issue in operations.*



## Photograph Descriptions

- \* 1. Preparing hole by removing loose material ,
- \* 2. After preparation ,
- \* 3. Bulkfilling with Belzona 4124 ,
- \* 4. Top coated with Belzona 4111 ,

## Application Situation

Forklift traffic over control and expansion joint areas.

## Application Method

The holes were cleaned out and filled with Belzona 4124. Once the holes were filled, it was top coated with Belzona 4111. FPA-1 System Leaflet was followed.

## Belzona Facts

Customer saved a lot of money because there is a tunnel under the areas where the repair was done. Concrete was an option, but it would be a long and costly repair, and would eventually fail again. It took 1 day of labor to do the work. This Belzona system was used because it is proven to work and last a long, long time.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve