

BELZONA 7111 ALIGNS NEW INDUSTRIAL EQUIPMENT

ID: 6329

Industry: *General Industry*
Application: *GSS-Gaskets, Seals and Shims*
Substrate: *Steel base, concrete floor*
Products: ** Belzona 7111 ,*

Customer Location: *Manufacturing Plant, FL, USA*
Application Date: *August 2016*

Problem

On going construction on and around these equipment could not be stopped. Application had to be performed diligently and in harmony with other construction activities. The depth of the pours ranged between 1.5in to 3in.



Photograph Descriptions

- * 1. View of the gap needed to be filled. ,
- * 2. Temporary wood dam and expansion joint. ,
- * 3. Pouring of first layer. ,
- * 4. After dam removal. ,

Application Situation

New factory expansion needed chocking of three recently installed machinery. Leveling of the equipment was critical as well as preventing water with salt residues from penetrating beneath the bases.

Application Method

The application was carried out in accordance with the Belzona Know-How System Leaflet GSS-12.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

Belzona Facts

The application was carried out in less than a day with no interruption to the operation of the plant.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

