

BELZONA PROTECTS LISTED BUILDING

ID: 633

Industry: Buildings & Structures
Application: WPA-Wall Problem Areas
Substrate: Masonry coated with Belzona® 3111
Products: * Belzona® 5151 (Hi-Build Cladding) ,
 * Belzona® 3111 (Flexible Membrane) ,

Customer Location: Local Council Contractors, Liverpool UK
Application Date: September 2001

Problem

Traffic, pollution and grime had discolored the facade of the building.



Photograph Descriptions

- * Before application ,
- * During application, surface conditioned ,
- * Completed application ,

Application Situation

Grade 1 Listed Building

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet WPA-1.

Belzona Facts

Eleven years previously this building had been coated in Belzona® 3111 to stop external water and damp ingress. After inspection it was revealed that although it had become very grimy the Belzona coating was still in very good condition and would continue to function. The client decided that rather than just cleaning it, a self cleaning coating from Belzona would be better. The building is still looking good four years later.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
 FS 695214
 ISO 14001:2015
 EMS 695213

Belzona products are
 manufactured under an ISO
 9000 Registered Quality
 Management System.

www.belzona.com


BELZONA®
 Repair • Protect • Improve