

# QUARRY BELT REPAIR

ID: 634

Industry: *Mining & Quarrying*  
Application: *SHM-Solids Handling Machinery*

Customer Location: *Local Depot, Manchester UK*  
Application Date: *June 2000*

Substrate: *Rubber*  
Products: *\* Belzona&copy; 2311 (SR Elastomer),*

## Problem

*600mm (23inch) tear in the belt*



## Photograph Descriptions

\* Large sand belt 600mm gash in the belt ,

## Application Situation

Sand Belt

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-1.

## Belzona Facts

The belt performed well until the plants closing in 2004.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve