

BELZONA REPAIRS DAMAGED TRUCK SCALES

ID: 6340

Industry: General Industry
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona 4111 (Magma Quartz),

Customer Location: Building materials manufacturer, Croatia
Application Date: August 2016

Problem

The concrete surface of the scale suffered severe damage due to the heavy traffic, weather conditions and leaking of fuel, oil etc. Customer needed to address this problem, but due to intensive production it was impossible to put the truck scale out of use for more than a day or two. Belzona offered to repair the most damaged parts of the scale (where the reinforcement bars are exposed), as a first phase, with possibility to resurface the whole scale in the next phase.



Photograph Descriptions

* 1. Damaged truck scale - overview 2. Detailed view on one of severely damaged areas 3. Application in progress 4. Completed application ,

Application Situation

Truck scales operates 12+ hours per day, 6 days per week. Trucks loaded with raw materials and end products are weighed in and out all the time.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

Belzona Facts

Having in mind the fact that truck scale operates 6 days per week there are very few alternatives. Customer was considering building another truck scale beside the old one, but Belzona gave him a better solution.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

