BELZONA COLD PLATE BONDING REINFORCES OFFSHORE DECK

ID: 6372

Industry: Oil & Gas

Application: Substrate:


Products:

Carbon steel
* Belzona 1121,

* Belzona 5811,

Problem

The customer had an integrity inspection performed on their steel decks as part of a life extension program. Several areas on two decks were noted to have thicknesses below the minimal thickness allowed. Some areas had holes which meant a loss of containment if there were an accidental spill.







Customer Location: Gulf of Mexico, USA

Application Date: September 2016



Photograph Descriptions

- * 1. Pitted and corroded deck.,
- * 2. Preparing deck and repair plate with border of Belzona 1121,
- * 3. Injecting Belzona 5811 (Immersion Grade) between repair plate and deck.,
- * 4. Completed application.,

Application Situation

Offshore platform had deck areas with 60% metal wall loss

Application Method

The application was carried out in accordance with Belzona BEL-CIS-100 Creating Irregular Shims and Method Statement for Cold Plate Bonding. All holes on deck were first repaired, then a perimeter bond was created with Belzona 1121. After Belzona 1121 was allowed to cure, Belzona 5811 was injected by single component airless spray into the dam created between the deck and repair plate.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA

www.helzona.com

Belzona Facts Belzona was chosen because it was evaluated as safer and more cost effective than conventional deck cutting and plate welding alternatives. Additionally, the Belzona solution is stronger than welding and eliminates the void where corrosion continues.