

BELZONA SAVES GULF OF MEXICO FROM POTENTIAL OIL SPILLAGE

ID: 6377


Industry: Oil & Gas
Application: FBC-Fans, Blowers and Compressors

Customer Location: Gulf of Mexico, USA
Application Date: November 2016

Substrate: Carbon steel
Products: * Belzona 9611 ,
* Belzona 1161 ,

Problem

All spilled fluids on the offshore platform drain to this lowest point. The sump was a last defense and served as a gravity separator in case any oil is spilled on the platform deck. If there were oil in the bottom of this sump, it would spill into the Gulf of Mexico. Fortunately, there was no oil in the sump as it had been skimmed off prior to blasting operations.



Photograph Descriptions

- * 1. Blistered and corroding sump pile. ,
- * 2. Through wall defect discovered during blasting operations. ,
- * 3. Defective area plugged with wood and Belzona 9611 to reduce leak. ,
- * 4. Cold plate bonding repair with Belzona 1161. ,

Application Situation

The customer had a blasting and painting contractor on board to carry out routine work. While abrasive blasting a sump, a large through wall defect was discovered.

Application Method

The application was carried out in accordance with Belzona Know How System Leaflet FBC-6 for sealing leaks. First, Belzona 9611 was used to plug over a wooden shim that reduced the leak to a weep. Secondly, Belzona 1161 was used to cold bond a 4"x4" steel plate onto the substrate and seal the leak completely. Belzona 1161 was further used to chamfer around the plate.

Belzona Facts

Both the contractor and asset owner were fortunate to have Belzona products for this application, already on board. A small amount of Belzona product was enough to contain a 40' x 36" column of water.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2024

