

HISTORIC TOWN HALL MADE SAFE WITH SYMPATHETIC BELZONA STONE REPAIRS

ID: 6383

Industry:
Application: WPA-Wall Problem Areas
Substrate: Concrete and Sandstone
Products: * Belzona® 4141 (Magma Build) ,

Customer Location: Local Authority, North Yorkshire, UK
Application Date: 2016

Problem

Failure of previous cementitious repairs was causing a safety risk to pedestrians in this busy seaside resort. Customer required a long-term solution that would cause minimal disruption.



Photograph Descriptions

* 1. Damaged architrave and capital 2. Repairs in progress 3. Completed repairs 4. Overview of completed work ,

Application Situation

Grade II* Listed Town Hall

Application Method

Application carried out in accordance with Belzona system leaflet WPA-4. The experienced contractors reformed the original profiles and used pigments to blend in the repairs to match the original stonework.

Belzona Facts

The customer is delighted with the Belzona repairs, which provided a quick, long term solution to the safety problem. The repairs blended in so well that the client is now looking to use the Belzona system on other buildings under their authority.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024