

# KEEPING AFLOAT WITH BELZONA

ID: 639

Industry: Oil & Gas  
Application: SOS-Ships and Offshore Structures

Customer Location: Oil Rig Operator.  
Application Date: March 2001

Substrate: Rubber  
Products: \* Belzona<sup>®</sup> 2311 (SR Elastomer),

## Problem

Damaged due to collision with other objects such as boats, flotsam etc.



## Photograph Descriptions

- \* Surface prepared ,
- \* Area marked up, ready for the Belzona ,
- \* Finished repair ,

## Application Situation

Sponson (An air bag or floatation device) attached to a fast rescue craft.

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet SOS-12.

## Belzona Facts

Every repair with Belzona here saves the purchase of a new sponson at a cost of £400.00. The added bonus was that the repairs could be done at sea allowing the rescue craft to remain in service. This method of repair was used until the craft were taken out of service.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA<sup>®</sup>**  
Repair • Protect • Improve