

BELZONA IMPROVES SAFETY WITH GRIP SYSTEM

ID: 6418

Industry: Buildings & Structures

Application: FPA-Floor Problem Areas

Substrate: Marble

Products:

* Belzona 4411 (Granogrip) ,




* Belzona 9221 (Surefoot Aggregate White) ,

Customer Location: Factory, Kirkop, Malta.

Application Date: May 2013

Problem

Marble stairs were very slippery, especially in wet conditions.



Photograph Descriptions

- * 1. Abraded nosing resulted in a non-effective solution ,
- * 2. Nosing ground by carbide discs ,
- * 3. Area Masked off ,
- * 4. Completed application ,

Application Situation

Factory main entrance steps.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. The steps were marked and the nosing ground with carbide discs. After masking off all the steps, Belzona 4411 was brushed on and sprinkled with Belzona 9221.

Belzona Facts

The previous solutions of abrading the nose or stick on strips had proved to be ineffective. Belzona 4411 reduced the potential for accidents as well as creating an aesthetically pleasing finish.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve