

# BELZONA REBUILDS WORN STONE STEPS

ID: 6425

**Industry:** Buildings & Structures  
**Application:** FPA-Floor Problem Areas  
**Substrate:** Stone  
**Products:** \* Belzona 4111 (Magma Quartz),

**Customer Location:** Prestigious school, Floriana, Malta  
**Application Date:** December 2016

## Problem

All the stone steps had become badly worn, uneven and sloping towards the front. This was a safety hazard. Due to the construction of the stone steps, it was not possible to repair with other traditional methods.



## Photograph Descriptions

- \* 1. Badly worn stone steps ,
- \* 2. Cleaned and Wooden formers installed ,
- \* 3. Steps filled up and leveled with Belzona 4111 ,
- \* 4. Finished Job ,

## Application Situation

Badly worn stone steps.

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1. Wooden formers were installed to help level the steps evenly.

## Belzona Facts

The application was done during Normal working hours closing only parts of the school, The other option was to remove and change the stone stairs and to do this they would have had to close the school during the construction period and would have been far more costly than the Belzona option.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve