

# EASY LINTEL REPAIR WITH BELZONA

ID: 6435

**Industry:** Buildings & Structures  
**Application:** WPA-Wall Problem Areas  
**Substrate:** Concrete and Steel  
**Products:** \* Belzona® 4141 Belzona® 4911 ,

**Customer Location:** Housing Association, Cleveland, UK  
**Application Date:** 2017

## Problem

The entire front face of the concrete "Boot" lintel had failed due to re-bar corrosion. The customer wanted a long-term solution without having the need to disturb the structure.



## Photograph Descriptions

- \* 1. Overview (after repair) ,
- \* 2 & 3. Damaged Lintel ,
- \* 4. Completed repair ,

## Application Situation

Residential Property

## Application Method

Application carried out in accordance with Belzona system leaflet WPA-4

## Belzona Facts

The application was completed in just 2 hours. Conventional replacement would have been costly, time consuming and disruptive. The customer has used Belzona 4141 before and is very happy with the results.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve