

Belzona Lines New Build Desalter with Belzona 1391T


ID: 6454

Industry: Oil & Gas
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Carbon Steel
Products: * Belzona 1391T,

Customer Location: Iraq
Application Date: January 2017

Problem

Newly fabricated vessel which was required to have an internal protective coating.



Photograph Descriptions

- * 1.Nozzle Insert ,
- * 2.2nd Coating ,
- * 3.Spark Test ,
- * 4.Final ,

Application Situation

Operating Temperature Min/Norm/Max:20/58/70 , Service /Crude Oil + Water + Sour Gas and specified with Belzona internal lining and nozzle insert.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5 and TCC-16b . Preformed nozzle inserts were created and bonded into small diameter nozzles to ensure continuity of protection.

Belzona Facts

Using the Belzona internal coating and nozzle inserts solution , the vessel will have a longer service life.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve