

BELZONA REPAIRS BROKEN EDGES OF ENGINE BLOCK


ID: 653

Industry: Oil & Gas
Application: ENC-Engines and Casings
Substrate: Cast Iron
Products: * Belzona® 1111 (Super Metal) ,

Customer Location: Oil production company, Egypt
Application Date: September 2005

Problem

The edge of the engine block was broken.



Photograph Descriptions

- * The broken edge of the block ,
- * Surface preparation ,
- * Rebuilding the broken edge using Belzona® 1111 ,
- * Block was repaired ,

Application Situation

Engine block

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet ENC-1.

Belzona Facts

Belzona easily repaired the broken edge of the block without heat distortion in only one hour of work.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve