

BELZONA RESTORES CORRODED COOLER COVER

ID: 656

Industry: Marine
Application: HEX-Heat Exchangers
Substrate: Steel
Products: * Belzona® 1311 (Ceramic R-Metal) ,
* Belzona® 1321 (Ceramic S-Metal) ,

Customer Location: Maritime company, Egypt
Application Date: March 2005

Problem

Both the inlet and outlet pipes on the cooler were totally corroded through with large holes in the body of the cover.



Photograph Descriptions

- * The cover ,
- * Rebuilding the division bar completed ,
- * Rebuilding the inlet and outlet pipes ,
- * Cover coated to provide overall protection ,

Application Situation

Cooler cover

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets HEX-3 & HEX-5.

Belzona Facts

Instead of being scrapped Belzona restored this cover, getting it back into service with added protection from future corrosion.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve