

BELZONA BUND SEALING TO ENSURE ENVIRONMENTAL COMPLIANCE

ID: 666

Industry: Commercial Facilities
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Concrete
Products: * Belzona® 4141 (Magma-Build) ,
* Belzona® 4131 (Magma-Screed) ,
* Belzona® 5231 (SG Laminate) ,

Customer Location: Commercial Vehicle Repair Shop
Application Date: September 2005

Problem

Legislation non-compliance due to newly constructed bund being porous due to construction materials, concrete base and 9 inch concrete block walls.



Photograph Descriptions

- * Porous bund floor and side wall ,
- * Introduction of wall to wall fillets ,
- * Wall penetrations sealed and fillet complete ,
- * Finished job ,

Application Situation

Bund floor and walls

Application Method

Application carried out in accordance with Belzona Know-How System Leaflet TCC-15.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

Belzona Facts

Original condition of bund meant that it failed the Environmental compliance guidelines (PPG 2). Belzona materials were easily applied to give a long term impermeable coating system.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

