

BELZONA REPAIRS LARGE HYDRAULIC RAM

ID: 668


Industry: *General Industry*
Application: *MPT-Mechanical Power Transmission*

Customer Location: *Hot Roll Mill for Steel Sheets, Macedonia*
Application Date: *October 2005*

Substrate: *Steel*
Products: ** Belzona® 1221 (Super E Metal) ,*

Problem

Many years in service had caused large vertical gouges to be worn into the ram



Photograph Descriptions

- * Surface preparation ,
- * Ready for application of Belzona ,
- * Finished repair ,

Application Situation

Large Hydraulic Ram

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet MPT-3.

Belzona Facts

Belzona was the only method of repair available for such a ram and without it the ram would have had to have been replaced. The application was completed for only 400 Euros, a tiny fraction of the cost of a new ram which would have had a lead time of more

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve

that 4 weeks taking a large amount of this mill off line.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

