

BELZONA SEALS ASH VALVE


ID: 674

Industry: *General Industry*
Application: *GSS-Gaskets, Seals and Shims*
Substrate: *Steel*
Products: ** Belzona® 2111 (D&A Hi-Build Elastomer),*

Customer Location: *Cement Works, Usje, Macedonia*
Application Date: *December 2003*

Problem

Poor sealing between the steel gate and the valve housing meant that there was a 2-3 mm gap all around the seal area.



Photograph Descriptions

- * Ash valve ,
- * Ash valve during repair ,

Application Situation

Cement plant ash valves

Application Method

Application was carried out in accordance with Belzona® Know-How System Leaflet GSS-5.

Belzona Facts

Although the ash valve was new the poor seal allowed ash to escape and pollute the surroundings. The client was delighted with the outcome of this upgrade which avoided the need to replace the valve. Subsequently 6 others were done in the same way.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve