

# BELZONA REPAIR OF ACCESS RAMP AND STEPS


ID: 693

**Industry:** Buildings & Structures  
**Application:** FPA-Floor Problem Areas  
**Substrate:** Old concrete  
**Products:** \* Belzona® 4131 (Magma-Screed) ,  
\* Belzona® 4411 (Granogrip) ,  
\* Belzona® 5231 (SG Laminate) ,

**Customer Location:** Local Council, United Kingdom  
**Application Date:** November 2004

## Problem

Much foot traffic and heavy weathering caused the steps and disabled access ramp of these public toilets to become damaged and worn. An inspection of the ramps according to the Disability Discrimination Act (DDA) found them to be unsafe and not compliant.



## Photograph Descriptions

- \* Worn steps were a health and safety hazard ,
- \* Prepared surface ,
- \* Surface rebuilt with Belzona® 4131 ,
- \* Completed project ,

## Application Situation

Heavily worn steps and disabled access ramp

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve

## Belzona Facts

The use of Belzona products was requested by the council in order to give a fast, long life, cost effective repair. The ability to bond and build up old concrete meant that the steps did not have to be completely removed and rebuilt. This ensured that the toilets would comply to the DDA standards. These heavily used toilets were quickly reopened to the public.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

