

# BELZONA WEATHERPROOFS AIRPORT FIRE STATION ROOF

ID: 696

Industry: *Buildings & Structures*  
Application: *RPA-Roof Problem Areas*  
Substrate: *Concrete*  
Products: *\* Belzona® 3131 (WG Membrane) ,*

Customer Location: *Airport, UK*  
Application Date: *May 2003*

## Problem

*This fire station roof was leaking and the local airport authority wanted to repair it and extend its life, rather than a full replacement.*



## Photograph Descriptions

\* 1. Roof to be coated  
2. The roof after cleaning and surface preparation  
3. Coated roof  
4. Completed application ,

## Application Situation

Airport fire station roof

## Application Method

Application was carried out in accordance with Belzona® System Leaflet RPA-1

## Belzona Facts

The unusual construction of this roof posed a problem for other roofing systems. Belzona was chosen as the solution, as the alternative was to completely replace the roof. 2 years on and the application is still in perfect condition.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve