

BELZONA SEALS LEAKING TRANSFORMER FLANGES

ID: 700

Industry: Power

Customer Location: Electricity Supplier, British Columbia, Canada

Application: TCC-Tanks and Chemical Containment Areas


Application Date: August 1990

Substrate: Mild steel

Products: * Belzona® 2211 (MP Hi-Build Elastomer) ,
* Belzona® 2221 (MP Fluid Elastomer) ,

Problem

Oil was leaking out between the flanges.



Photograph Descriptions

- * View of oil covered flange ,
- * Flanges degreased and blasted to provide a good rough surface profile ,
- * Application in progress with bolts being sealed first ,
- * Completed application ,

Application Situation

Electricity Transformer Flanges

Application Method

Application carried out in accordance with a modified version of Belzona Know-How Leaflet TCC-2.

Belzona Facts

Using Belzona allowed the repair to be completed without having to remove the top from the transformer, which would have resulted in many hours of outage time.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve