

# BELZONA SEALS INSULATOR LEAKS

ID: 702

Industry: Power  
Application: GSS-Gaskets, Seals and Shims  
Substrate: Porcelain and Aluminum  
Products: \* Belzona® 2121 (D&A Hi-Coat Elastomer) ,

Customer Location: Power Plant, British Columbia, Canada  
Application Date: August 2003

## Problem

Seal within insulators eroded and as a result oil leakage began to occur.



## Photograph Descriptions

\* Surface preparation in progress Surface preparation by grit blasting completed Completed application. ,

## Application Situation

Power Line Insulators

## Application Method

Application carried out in accordance with Belzona Know-How Leaflet GSS-3.

## Belzona Facts

Belzona products have been used for many of these types of sealing applications with tremendous success.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve