

BELZONA PROTECTS HYDROELECTRIC TURBINES

ID: 710

Industry: Power

Customer Location: Hydroelectric Power Plant, Czech Republic

Application: CEP-Centrifugal Pumps

Application Date: October 2004

Substrate: Cast Steel

Products: * Belzona® 1341 (Supermetalglide),

Problem

Erosion caused by entrained particles in the water, there was also corrosion damage present.



Photograph Descriptions

* 1. Damaged Turbine 2. Application Situation 3. Coated Blades 4. Completed Application ,

Application Situation

Two Kaplan Turbines

Application Method

The application was carried out in accordance with Belzona® Know-How System Leaflet CEP-10.

Belzona Facts

Belzona® 1341 was chosen for its excellent erosion protection, as well as enhancing the efficiency of the turbines.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve