

BELZONA EXTENDS LIFE OF CONDENSER EXPANSION JOINT

ID: 719

Industry: *Buildings & Structures*

Application: *CEP-Centrifugal Pumps*

Substrate: *Rubber.*

Products: ** Belzona® 2221 (MP Fluid Elastomer) ,*

Customer Location: *Power plant, Egypt.*

Application Date: *November 2005.*

Problem

Both sides, top and bottom, of the rubber flexible joint had deteriorated.



Photograph Descriptions

- * The deteriorated rubber joint ,
- * Surface preparation of the joint ,
- * Conditioning the surface ,
- * Belzona® 2221 applied ,

Application Situation

The rubber expansion joint of the main condenser of the plant.

Application Method

Application was carried out in accordance with modified version of Belzona® Know-How System leaflet SHM-9.

Belzona Facts

Belzona® 2221 was able to quickly and successfully repair the rubber joint on the spot, extending its life without disrupting operation of the plant.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve