

BELZONA GLAND HOUSING REBUILD

ID: 720

Industry: Power
Application: CEP-Centrifugal Pumps
Substrate: Cast Iron.
Products: Belzona® 1311 (Ceramic R-Metal)

Customer Location: Power plant , Egypt.
Application Date: October 2006.

Problem

Gland housing of the pump was badly worn and damaged due to mechaical failure.



Photograph Descriptions

* The damaged gland housing , * Preparing the housing , * Reforming the housing to its original dimensions , * Repair completed ,

Application Situation

Split casing water pump.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet CEP-2.

Belzona Facts

Belzona reformed gland housing back to original dimensions without heat and was completed in one day.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve