

BELZONA HELPS SWEET MANUFACTURER AGAIN AFTER 8 YEARS

ID: 737

Industry: General Industry
 Application: TCC-Tanks and Chemical Containment Areas
 Substrate: Steel & Belzona® 1321
 Products: * Belzona® 1321 (Ceramic S-Metal) ,

Customer Location: Sweet Manufacturer, Belgium
 Application Date: September 2005

Problem

The Belzona coating, applied 8 years previously, was still in good condition and had only suffered some discolouration. The client, however, wanted to apply a fresh coat of Belzona.



Photograph Descriptions

- * 8-year-old Belzona® 1321 coating ,
- * Another view of 8-year-old Belzona® 1321 coating ,
- * New Belzona® 1321 coating ,
- * Coated hatch ,

Application Situation

Mixing tank

Application Method

The Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

Belzona Facts

The client was so pleased that the original Belzona coating lasted 8 years that they once again contacted Belzona to re-coat the machine.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
 FS 695214
 ISO 14001:2015
 EMS 695213

Belzona products are
 manufactured under an ISO
 9000 Registered Quality
 Management System.

www.belzona.com


BELZONA
 Repair • Protect • Improve